

NUUO NVRsolo Plus 3



Trusted Video Management



Release Version 4.0.0.150 2024 Aug 26th

Version Overview

	Type	Item	Version
Firmware	Applied models	NP-2040S	
		NP-2080S	4.0.0.150
		NP-2160S	
Built-in Device Pack		24.3.0.5	
Application	Install Wizard	6.1.705.23	
	Remote Live Viewer	6.1.705.23 / MainConsole Client pack 8.9.0	
	Playback System		
	Backup System		
	Verification Tool		
Offline License Tool		2.0.4.4	

Enhancements

- Expanded the date & time limitation for the local Log Viewer, the local Install Wizard and the local Playback panel to 2036.

Bugs Fixed

1. **System Loading Icon:** Restored functionality for smoother user experience.
2. **HDMI Audio Output:** Fixed issues to ensure reliable audio output via HDMI.
3. **Daylight Saving:** Resolved issues with daylight saving time adjustments.
4. **Local Display Output:** Abridged selection of local display outputs.
5. **Camera Preview:** Resolve issues of camera preview functionality on the local setting panel.
6. **NVR Motion Detection UI:** Adjusted the user interface for motion detection settings on the local end.
7. **Default Loading Message:** Updated the hint message displayed before loading to default settings.
8. **System Information Panel:** Refined information display on the local side.

Known Issues

- Please build a volume first before using NVRsolo Plus 3.
- With WD 4TB Purple HDDs, SoloPlus series may hang for 2 or more minutes after creating a RAID 0 volume. The duration depends on the number of the WD Purple HDDs, and the issue was not observed with Seagate 4TB HDDs.

Suggestions

- Suggest using the client pack of MainConsole for better liveview, playback, backup and verification experience.



Release Version 4.0.0.148 (Dec, 2023)

Version Overview

Type	Item	Version
Firmware	NVR	NP-2040S
		NP-2080S
		NP-2160S
Application	Camera Package	
	DP v23.6	
	Install Wizard	6.1.705.23
	Remote Live Viewer	
	Playback System	
	Backup System	
	Verification Tool	6.1.705.0
	Offline License Tool	2.0.4.4

Enhancements

1. In the absence of a volume, license import functionality will be unavailable through both the web interface and local UI.
2. Removed the local UI export playback program interface.
3. Fix the description on the local display for loading the default configuration password.

Bugs Fixed

1. An internal 500 server error occurs when attempting to upgrade the device via the web interface.
2. Fixed an issue where the year setting in both the web and local UI was limited to 2023.
3. When changing the IP mode from Static IP to DHCP Server, incorrect information is displayed on the user interface.

Known Issues

Stand Alone NVRsolo Plus 3

- The description on the web for loading the default configuration password is incorrect.



Release Version 4.0.0.147 (Nov, 2023)

Version Overview

Type	Item	Version
Firmware	NP-2040S	04.0000.0000.0147
	NP-2080S	
	NP-2160S	
	Camera Package	DP v23.6
Application	Install Wizard	6.1.705.23
	Remote Live Viewer	
	Playback System	
	Backup System	
	Verification Tool	6.1.705.0
	Offline License Tool	2.0.4.4

Enhancements

1. Modify the shutdown description on the Japanese version webpage to ensure accuracy and clarity.
2. Disable the local UI built-in motion detection interface as it is no longer supported.
3. Implement support for audio playback through the backplane and HDMI ports.
4. Introduce a new feature on the web page and local UI to enable users to select the desired audio output interface (HDMI or AUX).
5. Integrate support for P2P services to enhance user connectivity and accessibility.

Technical Updates

1. Upgrade PHP version to 8.2.10, Lighttpd version to 1.4.71, and OpenSSL version to 1.1.1u to bolster security measures and optimize performance.
2. Update the webpage copyright version to reflect the latest information.

Bugs Fixed

1. Resolved the screen retention issue.
2. Rectified issues related to recording schedule settings.

Stand Alone NVRsolo Plus 3

3. Addressed the inability to modify the web port.
4. Corrected the mismatch between email snapshot channel names.
5. Fixed the erroneous export of user privileges.
6. Resolved the incorrect time zone display in RLV.
7. Addressed the issue with loading configuration files.
8. Fixed the password reset functionality.
9. Rectified the issue of garbled characters appearing when loading the system default configuration.
10. Corrected the abnormal settings for daylight saving time and the NTP server.

Known Issues

1. When changing the IP mode from Static IP to DHCP Server, incorrect information is displayed on the user interface.
2. An internal 500 server error occurs when attempting to upgrade the device via the web interface.



Trusted Video Management

Release Version 4.0.0.119 (2022/12)

Version Overview

Type	Item	Version
Firmware	NVR	NP-2040S
		NP-2080S
		NP-2160S
Application	Camera Package	
	DP v23.1	
	Install Wizard	6.1.705.23
	Remote Live Viewer	
	Playback System	
	Backup System	
	Verification Tool	6.1.705.0
	Offline License Tool	2.0.4.4

Bugs Fixed

1. Digital PTZ
2. Emergency record
3. Install Wizard camera setup checkbox issue
4. Playback blackout issue
5. Time change after reboot
6. Abnormal time zone

Known Issues

1. DHCP Server
2. P2P Server

Release Version 4.0.0.117 (2022/11)

Version Overview

Type	Item	Version
Firmware	NVR	NP-2040S
		NP-2080S
		NP-2160S
Application	Camera Package	
	Install Wizard	
	Remote Live Viewer	
	Playback System	
	Backup System	
	Verification Tool	
		6.1.705.23
		6.1.705.0
		2.0.4.4

Bugs Fixed

1. USB supports keyboard
2. Auto search issue
3. User group issue
4. Load default issue

Known Issues

1. DHCP Server
2. P2P Server
3. Abnormal time zone

Release Version 4.0.0.115 (2022/10)

Version Overview

Type	Item	Version
Firmware	NVR	NP-2040S
		NP-2080S
		NP-2160S
Application	Camera Package	
	DP v22.7	
	Install Wizard	6.1.705.23
	Remote Live Viewer	
	Playback System	
	Backup System	
	Verification Tool	6.1.705.0
	Offline License Tool	2.0.4.4

Bugs Fixed

1. Local display H.264/265
2. language issue
3. NTP Server
4. Modify camera parameters
5. Camera disconnection and automatic reconnection
6. Export import config

Known Issues

1. USB support Keyboard
2. DHCP Server
3. P2P Server

Release Version 4.0.0.111 (2022/09)

Version Overview

Type	Item	Version
Firmware	NVR	NP-2040S
		NP-2080S
		NP-2160S
Application	Camera Package	
	DP v22.7	
	Install Wizard	6.1.705.23
	Remote Live Viewer	
	Playback System	
	Backup System	
	Verification Tool	6.1.705.0
	Offline License Tool	2.0.4.4

Bugs Fixed

1. A08 (I/O Box) supported
2. Add/Remove License
3. CMS supported

Known Issues

1. Local I/O not supported
2. P2P not support
3. Abnormal time zone setting

Release Version 4.0.0.110 (2022/09)

Version Overview

Type	Item	Version
Firmware	NVR	NP-2040S
		NP-2080S
		NP-2160S
Application	Camera Package	
	DP v22.7	
	Install Wizard	6.1.705.23
	Remote Live Viewer	
	Playback System	
	Backup System	
	Verification Tool	6.1.705.0
	Offline License Tool	2.0.4.4

Bugs Fixed

1. Local display H.265

Known Issues

1. I/O not supported
2. P2P not support
3. Abnormal time zone setting
4. License function confirmation

Release Version 4.0.0.108 (2022/08)

Version Overview

Type	Item	Version
Firmware	NVR	NP-2040S
		NP-2080S
		NP-2160S
Application	Camera Package	
	Install Wizard	
	Remote Live Viewer	
	Playback System	
	Backup System	
	Verification Tool	
Offline License Tool		2.0.4.4

Known Issues

1. I/O not supported
2. P2P not support
3. Abnormal time zone setting
4. License function confirmation
5. Local display H.265 not available